

## (Qty: 3) Trumpf Laser Marking Systems

Asset ID: 29560

## **Configuration:**

Trumpf Laser Marking Systems Lot of 3 Laser Marking Systems:

- Vectormark (VMC) TruMark 7000 (1)
- TruMark 6000 (2)
- One laser not working due to water leak 2004 Vintage



## **More Photos on Following Pages**

To our knowledge, the information contained in this data sheet is accurate, but it may contain errors and we do not warrant the completeness or accuracy of this data.

Interested parties may contact Bridge Tronic Global for additional information at +1 949.396.1395 or sales@bridgetronic.com

Visit our website at: www.bridgetronic.com



QUICK LEAD TIMES




QUALITY



COMPETITIVE PRICING
































Interested parties may contact Bridge Tronic Global for additional information at +1 949.396.1395 or sales@bridgetronic.com



























Interested parties may contact Bridge Tronic Global for additional information at +1 949.396.1395 or sales@bridgetronic.com












COMPETITIVE PRICING



















Interested parties may contact Bridge Tronic Global for additional information at +1~949.396.1395 or sales@bridgetronic.com















Interested parties may contact Bridge Tronic Global for additional information at +1 949.396.1395 or sales@bridgetronic.com






























Interested parties may contact Bridge Tronic Global for additional information at +1 949.396.1395 or sales@bridgetronic.com















Interested parties may contact Bridge Tronic Global for additional information at +1 949.396.1395 or sales@bridgetronic.com







